

Imray Correction Notice

27 July 2012

ICE1-1

Chart E1 WGS 84

Edition Jun 2011

Date of printing Jun 2011

The following corrections should be noted:

1 Controlling depths in marinas and harbours

Controlling depths for the following marinas and harbours are reportedly as follows:

Horta north basin 4m shoaling to 3m at the head of the basin

Horta south basin 6m

Vila do Porto 4m at south end, shoaling to 3m mid basin and 1m at the north end

Vila Franca do Campo 3m shoaling to 2m north of the inner breakwater

Vila da Praia 2.5m at entrance, shoaling as you head south into the harbour (ILNW 342/11)

2 Praia da Vitória (Plan F)

The channel into the marina at Praia da Vitória is marked by small unlit yellow buoys. (ILNW 343/11)

3 Horta (Plan B)

The pinnacle rock shown to the east of the ferry pier is an approximate position only. Boats drawing more than 3m are therefore advised to avoid this area entirely. (ILNW 237/12)

4 Vila Franca do Campo (Plan I)

Amend contact email address to marinaem@sapo.pt (ILNW 290/12)

5 Praia da Vitória (Plan F)

Amend contact email address to marina@cmpv.pt (ILNW 291/12)